

Product Change Notification

1044

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2000. Third-party brands and names are the property of their respective owners.



Product Change Notification

Change Notification #: 1044

Change Title: Discontinuance of Intel S21152BA PCI –to- PCI Bridge

and the 21A5204 Evaluation Board

Date of PCN Publication: October 19, 2000

Type of Change Notification:

Product Discontinuance

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

Product Discontinuance Program Support Begins: October 19, 2000

Last Product Discontinuance Order Date: No orders will be accepted

Last Product Discontinuance Shipment Date: No additional product will be shipped

Description of Change to the Customer:

S21152BA Intel bridge product has a noise sensitivity that may affect some customer applications. Since Intel cannot predict which customers may have issue, the product is being discontinued immediately. Intel is requesting return of all S21152BA material.

The 21A5204 Evaluation Board for the S21152BA is also being discontinued.

Customer Impact of Change and Recommended Action:

- (1) Do not design-in the S21152BA
- (2) Return any S21152BA material through the RMA process
- (3) Intel will cancel all existing orders for S21152BA
- (4) Use the 21152-AB. The Last Order date for this product has been extended to December 31, 2001
- (5) Intel plans to introduce an S21152BB replacement part in the second half of 2001



Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	MM#	Recommended	Recommended		
		Replacement	Replacement MM#		
21A5204	829637	21A5203	821765		

Component Products Table

Affected Product Code	MM#	Recommended	Recommended
		Replacement	Replacement MM#
S21152BA	827717	21152-AB	821298

Reference Documents / Attachments:

Document: Location:

21152AB and S21152BB Differences Application Note (278329-002).

http://developer.intel.com/design/bridge/applnots/278329.htm

PCN Revision History:

Date of Revision: Revision Number: Reason: